



WARPING MILL




WM09022012V3

Parts List




TOOLS



Hint

To make assembly easier use candle wax on the screws.

Hard



Easy



Hardware List



X4




X6




X6





X10



X4



X2



X2

Before Commencing

Read the instructions completely, identify the parts and note the assembly sequence. Then use the fine sandpaper supplied to remove any sharp corners or edges.


Finishing the Wood

We recommend that the wood surfaces be waxed before assembly. This protects the kiln dried wood from climatic changes and enhances the beauty of the wood. Avoid waxing the dowel ends or holes.

For the Ultimate Finish


The Ashford Wax Finish will enhance the natural colours and beauty of the native New Zealand Silver Beech timber which has a lovely variety of colour and grain.

Step 1




X4

Step 2




X2


Step 3




Step 4




Step 5




Step 6




Step 7





Step 8



Step 9



Step 10



*Optional accessory Ashford Spinning Wheel Oil

